

## Twin Screw Cargo Pump

A.1027

### Problem

Pump in very bad condition. Casing, insert and rotors heavily attacked by bi-metallic corrosion.

### Place & performer

Pireaus, Greece

Wencon Workshop Partner, KME, Pireaus, Greece

### Application method

Rebuilding and machining of Cargo Pump.

### Application date:

October 2014

### Products recommended

[Wencon Rapid or Cream](#)

[Wencon Hi-Temp](#)

[Wencon Cleaner](#)

[Wencon Application tools](#)

### Pictures

1. Screw chambers attacked by corrosion.
2. After refurbishment, parts are machined to original size and clearance.
3. Chambers rebuild with Wencon Rapid and Hi-Temp, ready for machining
4. Machining after alignment completed.

