WENCON®



Product Information

Wencon Repair Kits for Marine

Wencon Repair Kits are available in different sizes, depending on the size and age of the vessel.

Covers most aspects of emergency repairs and long lasting maintenance. Suitable for all ships, where repairs and maintenance are carried out frequently. This on-board first aid kit contains a technical manual with detailed application data sheets, which support you fully with repairs, planned maintenance and improvements on board the vessel.







| Product No. | The standard Wencon Repair Kits contain: | Kit 1 | Kit 2 | Kit 3 | Kit 4 | Tanker Kit | Your kit |
|-------------|---|------------|-------------|------------|------------|---------------|-------------|
| 1010 | Wencon Cream, 1 kg | 1 set | | | | | |
| 1000 | Wencon Rapid, 1 kg | 1 set | 1 set | | | | |
| 1005 | Wencon Rapid, 8 x 125 g | 1 set | 1 set | 1 set | 1 set | | |
| 1020 | Wencon Coating, white, 0,5 kg | 2 set | 1 set | 1 set | | | |
| 1030 | Wencon Coating, blue, 0,5 kg | 2 set | 1 set | 1 set | | | 4 |
| 1050 | Wencon Hi-Temp, yellow, 0,5 kg | 1 set | | | | | |
| 1060 | Wencon Hi-Temp, green, 0,5 kg | 1 set | 1 set | 1 set | | | |
| 1040 | Wencon Putty, 8 x 125 g | 1 set | 1 set | 1 set | 1 set | | |
| 1042 | Wencon Putty, 4 x 125 g | | | | | 1 set | |
| 1044 | Wencon Pipe Tape 2 unit, 10 x 350 cm | | | | | | |
| 1045 | Wencon Pipe Tape 5 unit, 5 x 150 cm | 1 box | 1 box | 1 box | 1 box | | |
| 1046 | Wencon Pipe Tape 4 unit, 5 x 350 cm | 1 box | 1 box | | | 1 box | 1 |
| 1070 | Wencon Exhaust Repair Kit, 2 x 250 g | 1 box | 1 box | 1 box | 1 box | | |
| 1014 | Wencon UW Cream, 0,5 kg | 1 set | | | | 2 set | |
| 1035 | Wencon UW Coating, orange, 0,5 kg | 1 set | | | | 2 set | |
| 1036 | Wencon UW Coating, brown, 0,5 kg | | | | | 2 set | |
| 1016 | Wencon Ceramic Cream, 1 kg | | | | | 1 set | |
| 1017 | Wencon Ceramic Coating, light grey 0,5 kg | | | | | 1 set | |
| 1018 | Wencon Ceramic Coating, light green, 0,5 kg | | | | | 1 set | |
| 1100 | Wencon Cleaner, 0,5 l | 3 set | 2 set | 1 set | 1 set | | |
| 1104 | Wencon Bio Cleaner, 0,75 l | | | | | | |
| 1110 | Wencon Release Agent, 50 g | 1 box | 1 box | 1 box | 1 box | | |
| 1120 | Wencon Reinforcement Tape, 5cmx10m | 3 rolls | 2 rolls | 2 rolls | 1 roll | 6 rolls | |
| 1122 | Wencon Reinforcement Tape,10cmx20m | | | | | 1 roll | |
| 1150 | Wencon Aggregate No. 24, 1,5 kg | | | | | | |
| 2805 | Wencon Application Tools | 1 set | 1 set | 1 set | 1 set | 1 set | |
| 2808 | Wencon Fixation Tools | | | | | 1 set | |
| | Wencon Manual | 1 pcs. | 1 pcs. | 1 pcs. | 1 pcs. | 1 pcs. | |
| 1250 | Rotating Blaster single | | 1 | 1 | | 1 | |
| 1252 | Rotating Blaster duo | | | | | | |
| 1254 | Rotating Blaster tris | | | | | | |
| | Plywood Box | 1 large | 1 medium | 1 small | 1 small | 1 small | |

The Wencon Repair Kit is supplied in a strong plywood box suitable for shipping and storage on board. The Wencon Repair Manual is available for free download from our web page, in different languages.

| Product numbers: IMPA no. | | | |
|---------------------------|--|--|--|
| Repair Kit No. 1 | 812341 | 75.553.70 | |
| Repair Kit No. 2 | 812331 | 75.553.71 | |
| Repair Kit No. 3 | 812332 | 75.553.72 | |
| Repair Kit No. 4 | 812333 | 75.553.73 | |
| Гапker Kit | 812326 | N/A | |
| | Repair Kit No. 1 Repair Kit No. 2 Repair Kit No. 3 Repair Kit No. 4 Tanker Kit | Repair Kit No. 1 812341 Repair Kit No. 2 812331 Repair Kit No. 3 812332 Repair Kit No. 4 812333 | |

WENCON ApS • Jyllandsvej 15 • DK-5400 Bogense •

Phone +45 6481 1010 • wencon@wencon.com • www.wencon.com



Repair Management Nederland B.V. Jade 300 NL-3316 LJ Dordrecht Tel. +31 85 27 32 216 E-mail: wencon@wencon.nl

Web: www.wencon.nl



WENCON PRODUCTS

| WENCO | N PRODUCTS | | | | | | | |
|---|--|---|------------------------------------|--|--|--|--|--|
| No. 1010 | Wencon Cream, 1 kg unit | IMPA No. 812335 | ISSA No. 75.553.20 | | | | | |
| | s a basic two-component, epoxy compound with a wide | | | | | | | |
| 0 ' | d and corroded machine and metal parts. Typical applica age faces, roller bearing seats, worn shafts, hydraulic ram | | ımp housings, impellers, | | | | | |
| No. 1000 | Wencon Rapid, 1 kg unit | IMPA No. 812347 | ISSA No. 75.553.21 | | | | | |
| No. 1005 | Wencon Rapid 8, 8x125 g unit | IMPA No. 812343 | ISSA No. 75.553.22 | | | | | |
| | a fast curing, two-component, epoxy compound with a | | | | | | | |
| | pical applications as for Wencon Cream. | 8. o. all. | | | | | | |
| No. 1020 | Wencon Coating, white, 500 g unit | IMPA No. 812337 | ISSA No. 75.553.10 | | | | | |
| No. 1030 | Wencon Coating, blue, 500 g unit | IMPA No. 812338 | ISSA No. 75.553.11 | | | | | |
| | is a two-component, liquid epoxy coating suitable for a ebuilt after deterioration, protection of tanks, pumps, va orrosion. | | | | | | | |
| No. 1050 | Wencon Hi-Temp, yellow, 500 g unit | IMPA No. 812345 | ISSA No. 75.553.12 | | | | | |
| No. 1060 | Wencon Hi-Temp, green, 500 g unit | IMPA No. 812346 | ISSA No. 75.553.13 | | | | | |
| Wencon Hi-Temp is a high performance two-component, liquid epoxy coating developed for applications in high load areas. | | | | | | | | |
| No. 1040 | Wencon Putty, 8x125 g unit | IMPA No. 812342 | ISSA No. 75.553.40 | | | | | |
| No. 1042 | Wencon Putty, 4x125g unit | IMPA No. 812329 | ISSA No. N/A | | | | | |
| | a very quick curing, two component, epoxy compound s | | | | | | | |
| multipurpose epoxy paste is ideal for wide range of emergency repairs where an ultra quick curing and mouldable compound is required. | | | | | | | | |
| No. 1044 | Wencon Pipe Tape, 2 units (10x350 cm) | IMPA No. 812328 | ISSA No. N/A | | | | | |
| No. 1045 | Wencon Pipe Tape, 5 units (5x150 cm) | IMPA No. 812344 | ISSA No. 75.553.30 | | | | | |
| No. 1046 | Wencon Pipe Tape, 4 units (5x350 cm) | IMPA No. 812348 | ISSA No. 75.553.31 | | | | | |
| | pe is a fast curing pipe repair bandage especially formula rrosion porosity in piping carrying water, oil, steam, mos | | tive repairs of cracks, leaks, | | | | | |
| No. 1070 | Wencon Exhaust Repair Kit, 2x250g | IMPA No. 812340 | ISSA No. 75.553.25 | | | | | |
| | Repair is a one component steel cold weld product that | | | | | | | |
| is exposed to ten boilers. | nperatures up to 1300° C. Typical applications include er | ngine heads, blocks and man | ifolds, as well as furnaces and | | | | | |
| No. 1014 | Wencon UW Cream, 500 g unit | IMPA No. 812334 | ISSA No. 75.553.91 | | | | | |
| | sed cream for applying under water or direct on wet surf | | 700137 | | | | | |
| No. 1035 | Wencon UW Coating, orange, 500 g unit | IMPA No. 812336 | ISSA No. 75.553.92 | | | | | |
| No. 1036 | sed coating for applying under water or direct on wet su | | ICCA NIO NI/A | | | | | |
| | Wencon UW Coating, brown, 500 g unit sed coating for applying under water or direct on wet sur | IMPA No. 812327 | ISSA No. N/A | | | | | |
| No. 1016 | Wencon Ceramic Cream, 1 kg unit | IMPA No. 812592 | ISSA No. N/A | | | | | |
| | d for repair and rebuilding of deteriorated metal parts ex | | 10011110111111 | | | | | |
| No. 1017 | Wencon Ceramic Coating light grey, 500g | IMPA No. 812593 | ISSA No. N/A | | | | | |
| No. 1018 | Wencon Ceramic Coating light green, 500g | IMPA No. 812594 | ISSA No. N/A | | | | | |
| The cost effectiv | e coating product for general repair, maintenance and p | | ed to excessive wear. | | | | | |
| No. 1100 | Wencon Cleaner, 0,5 litre unit | IMPA No. 812349 | ISSA No. 75.553.01 | | | | | |
| Degreasing agen | t used prior to application of epoxy compounds and coa | itings. | | | | | | |
| No. 1104 | Wencon Bio Cleaner, 0,75 litre unit | IMPA No. N/A | ISSA No. N/A | | | | | |
| | t used prior to application of epoxy compounds and coa | | | | | | | |
| No. 1110 | Wencon Release Agent, 50 g unit | IMPA No. 812350 | ISSA No. 75.553.60 | | | | | |
| | ed to prevent adhesion of epoxy compounds and coatin | ~ | TOO A DI ME ME 2 MO | | | | | |
| No. 1120 | Wencon Reinforcement Tape, 0,05 x 10 m | | ISSA No. 75.553.50 | | | | | |
| No. 1122 | Wencon Reinforcement Tape, 0,10 x 20 m | | ISSA No. N/A | | | | | |
| _ | ' | | | | | | | |
| | | | | | | | | |
| | To reinforcing repairs made with epoxy compounds and Wencon Aggregate No. 24, 1,5 kg and granulates for non-slip surfacing and wear resistant of | IMPA No. N/A | ISSA No. N/A | | | | | |
| Silica carbide bas | Wencon Aggregate No. 24, 1,5 kg sed granulates for non-slip surfacing and wear resistant c | IMPA No. N/A oating applications. | | | | | | |
| Silica carbide bas No. 2805 | Wencon Aggregate No. 24, 1,5 kg | IMPA No. N/A oating applications. IMPA No. 812595 | ISSA No. N/A ISSA No. 75.553.80 | | | | | |

IMPA No. 812596

ISSA No. N/A

Selection of tools to support and secure Wencon products to the damaged part.

Wencon Fixation Tools

No. 2808