# **RMN NEWSLETTER**

**WENCON Scrubber Pipe** 

Wencon developed special Scrubber Pipe

Over the years we assist many exhaust

gas scrubber manufacturers with pro-

blems as corrosion in the scrubber, corrosion damage in the steel end pipe which

**Repair Kit** 

Repair Kits.

#### **WENCON**

Especially in a difficult time as we are faced with at this moment the Wencon Repair Kits shows it advance for the ship crew. The crew has to stay on board to prevent contamination with Corona. This means they have to do all kind of maintenance jobs and repairs without having assistance from service engineers from shore on board.

### The WENCON Repair Kit these days

The Wencon Repair Kit is a great tool, equipped with the right 2-component products for many applications and a complete manual that guids the crew step-by-step through the repair process to have a successful repair job. Many vessels around the world are sailing today with a Wencon Repair Kit on board and have all the benefits. We have daily orders with refills for the used products of the Repair Kits what shows that the system works as it is developed for.

#### The WENCON assistance these days

Wencon, RMN and the global partners assist from behind their computer also many shipowners with repairs on board. We are able to communicate via different media systems such as Phone, E-mail, Skype, Facetime etc. and guide them through the repair process when questions are made or the crew has any doubts how to take care of the repair job. In this hard times we are here to be your back-up and support you as good as possible.

#### What can a WENCON Service Partner do

Also our Wencon Service Partners can act very quickly in case big repairs has to be done.

The ship can land for example a pump, the Wencon Service Partner make a pick-up at the quay, take care for the repair job at his workshop and returns the repaired item to the quay and the ship can take it safe on board.

In case a service engineer must come on board the Wencon Service Partners knows exactly how to act and assist in a safe way to prevent Corona contamination on board.

#### many applications and the crew step-by-step The problem with GRP/GRE pipes is that the pipe surface has e a successful repair job. to be completely dry for a repair application in the normal way. are sailing today with a

With **Wencon UW Products** this pipe repair jobs can be carried out even on a wet surface. The adhesion of the Wencon UW products is superb and the curing time is relatively short. Curing time can be reduced using infrared light.

goes through the hull (as wel seawater inlet as seawater outlet

pipes), vibration damage, and GRP/GRE pipe damages.

The UW products are tested with and suitable for infrared curing. Curing with infrared radiationcan reduce curing time significantly. Result can vary, depending on circumstances and equipment used.

The Wencon Scrubber Pipe Repair Kit is a great tool for the crew on board to make a decent repair on the scrubber GRP/ GRE Pipes and reduce downtime of the vessel.

The Scrubber Pipe Repair Kit is a great success. One big shipowner ordered already 100 of those Wencon Scrubber Pipe Repair Kits as an emergency system in case of.

## The Wencon Scrubber Pipe Repair Kits are available for pipe diameters of 250 - 500 - 1000 mm.

For corrosion problems in the scrubber system we can also assist and advise you how to repair this. We already have a good experience in this.





Repair Management Nederland B.V. – Jade 300 – 3316 LJ Dordrecht – Netherlands Phone +31 (0)85 27 32 216 – email info@rmn.eu - www.repairmanagement.nl

