

Repair of Valve manifold

Application:	Repair of Valve manifold
Place:	Vlissingen, NL
Date:	September 2016
Job and report done by:	Minderhoud Techniek, NL
Wencon products used:	UW Cream, UW Coating, Cleaner, appl. tools



1 & 2

Leaking manifold received at workshop in Vlissingen, with the purpose of temporary repair - due to long lead time of approx. 6 weeks. Manifold was dismantled and shot-blasted to sweat out salt, before application with Wencon UW products



3.

New bronze bushings are machined and fit in the manifold, using Wencon UW Cream and Wencon UW Coating. Wencon UW products are used, due to its enormous good adhesion and strength.



4.

After curing, the manifold is ready for use.

