

WENCON Repair Kit 8821

W⁺ WENCON®



Wencon GRE Pipe Repair Kit

Repair Kit for Temporary Repairs & Daily Maintenance

The Wencon GRE Pipe Repair Kit is designed to enable the crew to repair leaks on GRE type of Pipes using the Wencon Pipe-Wrap Method. Applying interchanging layers of Wencon UW Coating and Wencon Reinforcement Tape will seal the leak and produce a strong temporary repair, that will last until replacement or more permanent solution is possible.
Suitable for GRE Ballast Pipes and GRE Scrubber Pipes.

- For pipes <DN500

Article 108821 -> Wencon 8741

Advantages

- Repairs done by crew
- Adheres to GRE & Steel
- Scrubber Pipe (GRE)
- Ballast Pipe (GRE & Steel)
- Cargo Pipe Steel
- Cable Pipe
- Fast curing time
- Adheres in wet conditions
- No dew point issues anymore

Repair possibilities some examples

- Repair of a GRE pipe **DN500**, length 500mm. UW Coating and 3 layers of Reinforcement Tape (0,10x20m). **1 Pcs**
- Repair of a GRE pipe **DN250**, length 500mm. UW Coating and 3 layers of Reinforcement Tape (0,10x20m). **2 Pcs**

What does the kit contain of

- 6 pcs Wencon 1035 UW Coating Orange 0,5 kg
- 6 pcs Wencon 1036 UW Coating Brown 0,5 kg
- 3 pcs Wencon 1122 Reinforcement Tape 10 cm x 20 m
- 1 pcs Wencon 2805 Application Tools
- 1 pcs Tercoo Duo Disc 620101



Class
Type
Approved
products
by DNV-GL,
ABS, BV,
RINA

LOGISTICS
NO
DANGEROUS
GOOD
DOCUMENTS
NEEDED



BENELUX DISTRIBUTOR FOR WENCON

Repair Management Nederland B.V. – Jade 300 – 3316 LJ Dordrecht – Netherlands
Phone +31 (0)85 27 32 216 – email info@rmn.eu - www.rmn.eu - ww.wencon.nl